

**From:** Richard Rupert/R3/USEPA/US  
**Sent:** 2/11/2012 11:13:24 AM  
**To:** "john.smelko@cabotog.com" <john.smelko@cabotog.com>  
**CC:**  
**Subject:** Fw: Dimock - HW-16 - Sediment Filter

From: Richard Rupert/R3/USEPA/US  
To: John Smelko <john.smelko@cabotog.com>  
Cc: richard.fetzer@epa.gov  
Date: 02/11/2012 11:10 AM  
Subject: Fw: Dimock - HW-16 - Sediment Filter

John, Our contractor believes a sediment filter at the [REDACTED] residence was removed by Brent (your treatment equipment contractor) during the sampling and perhaps not replaced. It is possible of course that Brent returned later after our contractor left and replaced the filter.

I just wanted to be sure the [REDACTED] aren't without there filter.....

regards,  
Rupert

---

Richard Rupert,  
On-Scene Coordinator  
U.S. EPA  
1650 Arch Street - 3HS31  
Philadelphia, PA 19103  
(215) 814-3463 - office  
215 514-8773 - mobile  
rupert.richard@epa.gov